

Rockwell H- SERIES to CMC MDM H-Series Replacement Conversion Table

| Description | H-Series P/N | CMC P/N | CMC Outline Dwg | | Speed-Torque Curve | | MDM H-Series Motor Configuration File | | | |
|------------------------------------|----------------------------|-----------------------------------|-----------------|-----------------|--------------------|--|--|--|-----------------------------------|--|
| | | | | | | | MDMH-SeriesUltraMaster (Ultra 100/200) | | MDMH-SeriesUltraWare (Ultra 3000) | |
| Motor, 2000 Line Encoder | H-2005-K-H00AA | T0603P0101 | 33030-026 | | T0603P0 | | T0603P0MDMHMaster(H-2005).mtr | | T0603P0MDMHWare(H-2005).mxf | |
| Motor-24V Brake, 2000 Line Encoder | H-2005-K-H04AA | Consult Factory | Consult Factory | Consult Factory | | | | | | |
| Motor, 2000 Line Encoder | H-3007-N-H00AA | T0851C6100 | 31030-080 | | T0851C6 | | T0851C6MDMHMaster(H-3007).mtr | | T0851C6MDMHWare(H-3007).mxf | |
| Motor-24V Brake, 2000 Line Encoder | H-3007-N-H04AA | Consult Factory | Consult Factory | Consult Factory | | | | | | |
| Motor, 2000 Line Encoder | H-3016-N-H00AA | T0852C6100 | 31030-081 | | T0852C6 | | T0852C6MDMHMaster(H-3016).mtr | | T0852C6MDMHWare(H-3016).mxf | |
| Motor-24V Brake, 2000 Line Encoder | H-3016-N-H04AA | Consult Factory | Consult Factory | Consult Factory | | | | | | |
| Motor, 2000 Line Encoder | H-4030-P-H00AA | T1101E0100 | 32030-057 | | T1101E0 | | T1101E0MDMHMaster(H-4030P).mtr | | T1101E0MDMHWare(H-4030P).mxf | |
| Motor-24V Brake, 2000 Line Encoder | H-4030-P-H04AA | Consult Factory | Consult Factory | Consult Factory | | | | | | |
| Motor, 2000 Line Encoder | H-4030-M-H00AA | T1101B0101 | 32030-057 | | T1101B0 | | T1101B0MDMHMaster(H4030-M).mtr | | T1101B0MDMHWare(H4030-M).mxf | |
| Motor-24V Brake, 2000 Line Encoder | H-4030-M-H04AA | Consult Factory | Consult Factory | Consult Factory | | | | | | |
| Motor, 2000 Line Encoder | H-4050-P-H00AA | T1102E0101 | 32030-022 | | T1102E0 | | T1102E0MDMHMaster(H-4050).mtr | | T1102E0MDMHWare(H-4050).mxf | |
| Motor-24V Brake, 2000 Line Encoder | H-4050-P-H04AA | Consult Factory | Consult Factory | Consult Factory | | | | | | |
| Motor, 2000 Line Encoder | H-4075-R-H00AA | T1103H0100 | 32030-023 | | T1103H0 | | T1103H0MDMHMaster(H-4075).mtr | | T1103H0MDMHWare(H-4075).mxf | |
| Motor-24V Brake, 2000 Line Encoder | H-4075-R-H04AA | Consult Factory | Consult Factory | Consult Factory | | | | | | |
| Motor, 2000 Line Encoder | H-6100-Q-H00AA | T1402G0100 | 35030-003 | | T1402G0 | | T1402G0MDMHMaster(H-6100).mtr | | T1402G0MDMHWare(H-6100).mxf | |
| Motor-24V Brake, 2000 Line Encoder | H-6100-Q-H04AA | Consult Factory | Consult Factory | Consult Factory | | | | | | |
| Motor, 2000 Line Encoder | H-6200-Q-H00AA | T1405G0100 | 35030-006 | | T1405G0 | | T1405G0MDMHMaster(H-6200).mtr | | T1405G0MDMHWare(H-6200).mxf | |
| Motor-24V Brake, 2000 Line Encoder | H-6200-Q-H04AA | Consult Factory | Consult Factory | Consult Factory | | | | | | |
| Rockwell H-Series | H-6300 H-8350 H-8500 | MDM H-Series NOT AVAILABLE | | | | | | | | |

NOTE: ABS OPTION IS NOT AVAILABLE. DRIVE SOFTWARE ALLOWS FOR ALTERNATE COMMUTATION OPTION.